


Power Source
3 Phase 380/415V 50Hz



Meaning of marks

Mark	Parts name	Mark	Parts name
CF11, 2	Capacitor for FMi	Thi-R	Thermistor
CF01, 2	Capacitor for FMO	Tho-A	Thermistor
CH	Crankcase heater	Tho-D	Thermistor
CM	Compressor motor	Tho-R	Thermistor
CnA-W	Connector	Tr, TrO	Transformer
F	Fuse	Vai, Vao	Varistor
FM11, 2	Fan motor (Indoor unit)	CT1, 2	Current sensor
FM01, 2	Fan motor (Outdoor unit)	49Fi	Internal thermostat for FMi
LED1	Indication lamp (Green-Run)	49Fo1, 2	Internal thermostat for FMO
LED2	Indication lamp (Yellow-Check)	63H1	High pressure switch (for protection)
LED-G	Indication lamp (Green)	52C	Magnetic contactor for CM
LED-R	Indication lamp (Red)	X1-7, X01-06	Auxiliary relay
LM	Louver motor	PC	Photo coupler
SV	Solenoid coil (for control)	NR	Surge suppressor
SW	Back up switch (ON/OFF)	△	Terminal (F)
TB	Terminal block (Omark)	■	Connector
Thi-A	Thermistor		

Color mark

Mark	Color	Mark	Color
BK	Black	BK/IR	Black/Red
BL	Blue	BK/WH	Black/White
BR	Brown	OR/WH	Orange/White
GR	Gray	RD/WH	Red/White
OR	Orange	Y/GN	Yellow/Green
P	Pink		
RD	Red		
WH	White		