


Power source
1 Phase 220/240V 50Hz



Meaning of marks

Mark	Parts name	Mark	Parts name
CC	Capacitor for CM	Th-R	Thermistor
CFo	Capacitor for FMo	Tho-A	Thermistor
CH	Crankcase heater	Tho-D	Thermistor
CM	Compressor motor	Tho-R	Thermistor
CnA ~ W	Connector (Cmark)	TrO	Transformer
CT1	Current sensor	Val	Valve
F	Fuse	Vao	Varistor
FMi	Fan motor (Indoor unit)	20S	4-way valve solenoid
FMo	Fan motor (Outdoor unit)	49F1	Internal thermostat for FMi
LED1	Indication lamp (Green - Run)	49Fo	Internal thermostat for FMo
LED2	Indication lamp (Yellow - Timer/Check)	52C	Magnetic contactor for CM
LM	Louver motor	52X5, 6	Auxiliary relay
NR	Surge Suppressor	X01~07	Auxiliary relay
PC	Photo coupler	63H1	High pressure switch (for Protection)
SV1	Solenoid coil (for control)	63H2	High pressure switch (for control)
SW	Switch (ON/OFF)	△	Terminal (F)
SW3	Changeover switch	LED-G	Indication lamp (Green)
TB	Terminal block (Omark)	LED-R	Indication lamp (Red)
Th-A	Thermistor		

Color mark

Mark	Color	Mark	Color
BK	Black	BK/RD	Black/Red
BL	Blue	BK/WH	Black/White
BR	Brown	BL/WH	Blue/White
GR	Gray	BR/WH	Brown/White
OR	Orange	BR/WH	Brown/White
PK	Pink	OR/WH	Orange/White
RD	Red	RD/WH	Red/White
WH	White	Y/GN	Yellow/Green
Y	Yellow		